Mohammad Akhtar

From: Vella Keon at Transport

Sent: Monday, July 07, 2014 4:11 PM **To:** mohammadakhtar@fleetship.com

Cc: Rowena Grima

Subject: RE: Hako - North America Emission Control Area - Non Compliance to LSFO usage

requirement

Flag Status: Flagged

Dear Mr. Iqbal Akhtar

This is to confirm being in receipt of your advisory/notification forwarded through your local reps. received today 7 July.

According to the information provided, this Office has taken note that despite best efforts made to bring the vessel in compliance with the LS fuel requirement for the NA ECA area (whereby low sulphur compliant IFO has been acquired prior to departure from the last port of call), due to unforeseen circumstances (a faulty return line valve in the boiler fuel oil system) the low sulphur fuel acquired during this last port of call may be contaminated/mixed with HSFO, as such may not be compliant for use in the NA ECA area.

Having noted that the vessel current route, in accordance with MARPOL Annex VI reg 18.2.4 the vessel shall provide documented evidence to its Administration and the appropriate port authorities that attempts have been made to purchase compliant fuel oil in accordance with the voyage plan. Every effort shall be done to immediately make the necessary arrangements to acquire compliant low sulphur fuel at the first available opportunity.

The US port authorities after taking note of the circumstances of this case will then consider all the documented evidence submitted.

Kind regards

Keon Vella - Technical Compliance Superintendent

Technical Department

Merchant Shipping Directorate - Malta Transport Centre

Marsa MRS 1917 Malta

Tel: +356 21250360 Fax: +356 21241460 EMail: keon.vella@transport.gov.mt/ship-registration/ www.transport.gov.mt/superyacht-registration/



Transport Maita

CONFIDENTIALITY NOTICE:

This e-mail message (including any attachments thereto) is privileged and confidential to the addressee and is intended only for the use of the addressee or his authorised agent.

If you are not the named addressee:

- (i) you are hereby notified that any distribution or copying of this message is strictly prohibited;
- (ii) you may not read, copy, forward, disclose or otherwise use it or any part thereof in any manner whatsoever; and
- (iii) you are kindly asked to urgently notify us accordingly, by e-mail reply, or by fax or phone.

From: Rowena Grima [mailto:rowena.grima@fenlex.com]

Sent: 07 July 2014 09:26

To: Vella Keon at Transport

Subject: FW: Hako - North America Emission Control Area - Non Compliance to LSFO usage requirement

Dear Keon,

Please see the below email from clients of the registered vessel HAKO.

Clients look forward to receiving your feedback on this incident.

I look forward to hearing further from you.

Kind regards,

Rowena Grima

Head of Ship Registration Department



Fenech & Fenech Marine Services Ltd.

198, Old Bakery Street, Valletta Vt.T1455, Malta | **www.fenechlaw.com**T. +356 21 241 232 | F: +356 25 990 642 | M. +356 99 475 588 | <u>rowena.grima@fenlex.com</u>

A Please consider your environmental responsibility before printing this e-mail

From: Mohammad Akhtar [mailto:mohammadakhtar@fleetship.com]

Sent: 06 July 2014 07:02

To: Rowena Grima

Cc: FLEET-HK-QUALSAFE10; FLEET-HK-TECH10; Polatkan Obay; Murat Gezgin; Azmi Seçmen

Subject: Hako - North America Emission Control Area - Non Compliance to LSFO usage requirement

Ref.:-Hako

IMO No.-9691814

Subject:- North America Emission Control Area - Non Compliance to LSFO usage requirement

Dear Rowena,

Please note that vessel Hako headed to Vancouver (ETA 12th July), Canada and whose port of call may change to

Prince Rupert has reported mixing of LSFO on board with HSFO due to a faulty return line valve in the boiler fuel

oil system as a result of which all LSFO available onboard in LSFO settling and service tanks has got mixed

with HSFO. The only other low sulphur grade available onboard is LSMGO (32.8 MT) which is not sufficient for use

during NA ECA transit and needs to be kept as minimum reserve for operational safety.

In view of this incident, vessel will be in non-compliance of NA ECA requirement and Master has submitted attached report to Transport Canada and we would also submit relevant report to US EPA.

Please find attached BDN of LSFO that was available onboard when vessel departed Yangzhou for its intended

voyage to Vancouver for your reference and vessel's charterers are looking into arranging supply of compliant

fuel at first port of call.

Kindly bring above to Transport Canada's knowledge and revert with their acknowledgement / feedback to this Incident.

2

Best regards,
Mohammad Iqbal Akhtar
Technical Superintendent,
Fleet Management Limited, Hong Kong

Tel.:- +852 2298 8412 Mobile:- +852 9386 2907

email:- mohammadakhtar@fleetship.com

SAFE CREW, SAFE SHIPS, CLEAN SEAS

DISCLAIMER

The information in this email and any attachments are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you are not the intended recipient please notify the sender immediately using the sender email address and delete this email. You should not read or copy this e-mail, use it for any purpose, disseminate it or disclose its contents to any other person. Note that any possible personal views or opinions presented in this email are solely those of the author and do not necessarily represent those of the firm as this may be contrary to the firm policy and outside the scope of the employment of the individual concerned. The firm will not accept any liability in respect of such communication.

Although the firm has taken reasonable precautions to ensure no viruses are present in this email, the firm cannot accept responsibility for any loss or damage arising from the use of this email or attachments. Moreover, communication via email over the internet is not secure and messages may be read, manipulated or otherwise compromised by unknown third parties. The firm does not accept any responsibility for the correctness and completeness of the transfer of information contained in such communication nor for any delay of receipt.